

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 7

11201 Renner Boulevard Lenexa, Kansas 66219

1 5 SEP 2015

<u>CERTIFIED MAIL</u> RETURN RECEIPT REQUESTED

Article No.: 7002 0860 0006 5966 4609

Mr. Burt Bond Wastewater Treatment Plant Operator City of Rockaway Beach P.O. Box 315 Rockaway Beach, Missouri 65740

Dear Mr. Bond:

Re:

Findings of Violation and Order for Compliance (Order)

Docket Number: CWA-07-2008-0031

This letter is to remind you that the submittals required in accordance with Paragraph 34 of the Order are a copy of the sampling and analysis information of the influent and effluent, bench sheets, removal efficiency calculations, and letterhead data reports from the certified laboratory performing the analyses. In addition, you are required to send a copy of the DMRs you send to MDNR. This information was due to the U.S. Environmental Protection Agency on August 10, 2015. To date, I have not received anything from Rockaway Beach for this time period. Please submit this information in accordance with the submittal requirements in paragraphs 37 and 38 of the Order as soon as possible. Thank you.

If you have questions please call me at (913) 551-7492.

Sincerely,

Cynthia Sans
Compliance Officer
Water Enforcement Branch

Concurrence: H: WWPD\WENF\ 2015 Correspondence\Sans\Overdue		
Deliverables 09 15 Ltr.docx: ls:7051:9/14/15		
Name	Sans	Huffman
Branch	WWPD/WENF	WENF
Sign	(1)	OIA,
Date	9/14/16	9/14//5



WENF JUN 2 2 2015

CSE

CLEAN STREAM ENTERPRISE LLC Bert Bond

102 E Brown, Clever Mo. 65631 417-693-3590

May 29, 2015

Rockaway Beach WWTF MO-0108162 1000 Boys Camp Road

C: Cynthia Sans EPA
E. C. West DNR
Mayor Rockaway Beach

Dear Ms. Sans, Thank You for providing me with the complete compliance order. This will be a great help in providing you with information you need as well as planning our engineering needs that are about to begin. I was glad to see most of the items in Count 4 of the order are already done or waiting on funding.

Count 4, Section 22

- (a) All of the flow meters are being replaced in the plant and will be factory calibrated by their techs upon being installed.
- (b) Engineering has begun to solve the low D.O. levels in the ditches.
- (c) Both aeration ditches will be operable within the month.
- (d) A new U.V. system has been ordered to replace the old one that keeps failing and is hard to find parts for.
- (e) Drive belt covers are being modified to fit the new equipment and will be installed as soon as they are done.
- (f) Work is nearly funded to completely clean and replace the sand and any non functioning parts in the sand filter.

Count 5

I believe we have provided the proper information since we began to operate the facility but please advise us if we can do a better job.

Financial

The balance on the Regional Facilities Accounts continues to show steady growth and a reserve fund had been set up again for repair and replacement.

Count 6 Regional Bio-Solids Program

The City is now a member of the Tri Lakes Bio Solids Program and will not be land applying any more sludge.

Any question or concerns contact me anytime at 417-693-3590

Bert Bond

w 451 . .

Clean Stream Ent, LLC